

### Cabin Filter

Maker	Model	Application
<b>FB1001 ( OE No : 9713307000 )</b>		
KIA	PICANTO (MORNING)	
<b>FB1002 ( OE No : 971331E000 )</b>		
HYUNDAI	ACCENT (VERNA)	
<b>FB1003 ( OE No : 971331H000 )</b>		
KIA	CEED	
<b>FB1004 ( OE No : 971331U000 )</b>		
KIA	SORENTO	
<b>FB1005 ( OE No : 971332B010 )</b>		
HYUNDAI	SANTA FE	
<b>FB1006 ( OE No : 971332D100 )</b>		
HYUNDAI	LAVITA	
<b>FB1007 ( OE No : 971332E200 )</b>		
HYUNDAI	TUCSON	
<b>FB1008 ( OE No : 971332E250 )</b>		
HYUNDAI	TUCSON	
<b>FB1009 ( OE No : 971332E910 )</b>		
KIA	SORENTO	
<b>FB1010 ( OE No : 971332F000 )</b>		
KIA	CERATO	
<b>FB1011 ( OE No : 971332G000 )</b>		
HYUNDAI	SONATA	
<b>FB1012 ( OE No : 971332H000 )</b>		
HYUNDAI	ELANTRA	
<b>FB1014 ( OE No : 971332K000 )</b>		
KIA	SOUL	
<b>FB1015 ( OE No : 971332L000 )</b>		
HYUNDAI	i30	
<b>FB1016 ( OE No : 971333A000 )</b>		
HYUNDAI	TRAJET	
<b>FB1017 ( OE No : 971333J000 )</b>		
HYUNDAI	VERACRUZ	

### Cabin Filter

Maker	Model	Application
<b>FB1018 ( OE No : 971333K000 )</b>		
HYUNDAI	SONATA	
<b>FB1019 ( OE No : 971333SAA0 )</b>		
HYUNDAI	SONATA	
<b>FB1020 ( OE No : 971334F010 )</b>		
HYUNDAI	H100	
<b>FB1021 ( OE No : 971334L000 )</b>		
HYUNDAI	SOLARIS	
<b>FB1022 ( OE No : 971637A000 )</b>		
HYUNDAI	TRUCK	
<b>FB1023 ( OE No : 971637C001 )</b>		
HYUNDAI	HD160	
<b>FB1024 ( OE No : 971638D100 )</b>		
HYUNDAI	UNIVERSE	
<b>FB1025 ( OE No : 974064A900 )</b>		
HYUNDAI	H1 (STAREX)	
<b>FB1026 ( OE No : 976171C001 )</b>		
HYUNDAI	GETZ / CLICK	
<b>FB1027 ( OE No : 976174H000 )</b>		
HYUNDAI	H1 (STAREX)	
<b>FB1029 ( OE No : 971331E100AT )</b>		
HYUNDAI	ACCENT (VERNA)	
<b>FB1030 ( OE No : 97133C1000 )</b>		
HYUNDAI	SONATA	
<b>FB1031 ( OE No : 9761938100 )</b>		
HYUNDAI	SANTA FE	
<b>FB1032 ( OE No : 087902E250A )</b>		
HYUNDAI	TUCSON	
<b>FB1033 ( OE No : 976193D000 )</b>		
HYUNDAI	TUCSON	
<b>FB1034 ( OE No : 087901C000A )</b>		
HYUNDAI	ACCENT (VERNA)	

### Cabin Filter

Maker	Model	Application
<b>FB1035 ( OE No : 971332B005 )</b>		
HYUNDAI	SANTA FE	
<b>FB1036 ( OE No : 087902H000A )</b>		
HYUNDAI	ELANTRA	
<b>FB1037 ( OE No : 9761938000 )</b>		
HYUNDAI	AZERA	
<b>FB1038 ( OE No : 976171C200 )</b>		
HYUNDAI	GETZ / CLICK	
<b>FB1039 ( OE No : 97030H1742 )</b>		
HYUNDAI	TERRACAN	
<b>FB1040 ( OE No : 971332D200 )</b>		
HYUNDAI	ELANTRA	
<b>FB1041 ( OE No : 971443B000 )</b>		
HYUNDAI	EQUUS	
<b>FB1042 ( OE No : 97133D3000 )</b>		
HYUNDAI	CRETA	
<b>FB1043 ( OE No : 97133L1000 )</b>		
HYUNDAI	SANTA FE	
<b>FB2001 ( OE No : 0K2FA6152X )</b>		
KIA	CARENS	
<b>FB2002 ( OE No : 976194E000 )</b>		
KIA	BONGO (FRONTIER, K SERIES)	
<b>FB2003 ( OE No : 0K9A46152XA )</b>		
KIA	CREDOS	
<b>FB2004 ( OE No : 87139YZZ03 )</b>		
TOYOTA	RAV 4	
<b>FB2005 ( OE No : 0K55361C14 )</b>		
KIA	CARNIVAL	
<b>FB2006 ( OE No : 8713933010 )</b>		
LEXUS	RX350	
<b>FB2007 ( OE No : 97133B2000 )</b>		
KIA	SOUL	

## Cabin Filter

Maker	Model	Application
<b>FB2008 ( OE No : 97133C5000 )</b>		
KIA	SORENTO	
<b>FB2009 ( OE No : 97133D4000 )</b>		
KIA	OPTIMA (K5)	
<b>FB2010 ( OE No : 97134C6900 )</b>		
KIA	SORENTO	
<b>FB3001 ( OE No : P13271190 )</b>		
CHEVROLET / GM DAEWOO	LACETTI	
<b>FB3002 ( OE No : P93740495 )</b>		
CHEVROLET / GM DAEWOO	REZZO	
<b>FB3003 ( OE No : P96296618 )</b>		
CHEVROLET / GM DAEWOO	MAGNUS / EPICA	
<b>FB3004 ( OE No : P96435888 )</b>		
CHEVROLET / GM DAEWOO	AVEO / KALOS / GENTRA / NEXIA	
<b>FB3005 ( OE No : P96554378 )</b>		
CHEVROLET / GM DAEWOO	LACETTI	
<b>FB3006 ( OE No : 96449577 )</b>		
CHEVROLET / GM DAEWOO	AVEO / KALOS / GENTRA / NEXIA	
<b>FB3007 ( OE No : 96425700 )</b>		
CHEVROLET / GM DAEWOO	SPARK	
<b>FB3008 ( OE No : 95947238 )</b>		
CHEVROLET / GM DAEWOO	CRONOS	
<b>FB3009 ( OE No : EC96554378 )</b>		
CHEVROLET / GM DAEWOO	OPTRA	
<b>FB3010 ( OE No : 96440878 )</b>		
CHEVROLET / GM DAEWOO	WINSTORM	
<b>FB3011 ( OE No : 96190645 )</b>		
CHEVROLET / GM DAEWOO	NUBIRA	
<b>FB3012 ( OE No : 96207422 )</b>		
CHEVROLET / GM DAEWOO	LEGANZA	
<b>FB4001 ( OE No : P68111091A0 )</b>		
SSANGYONG	KORANDO	

### Cabin Filter

Maker	Model	Application
<b>FB4002 ( OE No : P6812008040 )</b>		
SSANGYONG	REXTON	
<b>FB4003 ( OE No : 6811021000 )</b>		
SSANGYONG	RODIUS	
<b>FB4004 ( OE No : 6923005400 )</b>		
SSANGYONG	KORANDO	
<b>FB5001 ( OE No : BP4K61J6XA )</b>		
MAZDA	Etc	
<b>FB5002 ( OE No : GJ6A61P11A )</b>		
MAZDA	2	
<b>FB5003 ( OE No : 7803A004 )</b>		
MITSUBISHI	ASX	
<b>FB5004 ( OE No : MR398288 )</b>		
MITSUBISHI	LANCER	
<b>FB5005 ( OE No : 27277EN025 )</b>		
NISSAN	QASHQAI	
<b>FB5006 ( OE No : 27891AX01A )</b>		
NISSAN	Etc	
<b>FB5007 ( OE No : 08R79SEA000A )</b>		
HONDA	ACCORD	
<b>FB5008 ( OE No : 80292SHJA41 )</b>		
HONDA	CIVIC	
<b>FB5009 ( OE No : 72880AG000 )</b>		
SUBARU	LEGACY	
<b>FB5010 ( OE No : CU1919 )</b>		
TOYOTA	CROWN	
<b>FB5011 ( OE No : 8713950060 )</b>		
TOYOTA	GS300	
<b>FB5014 ( OE No : 8713912010 )</b>		
TOYOTA	AVENSIS	
<b>FB5015 ( OE No : 9586164J00 )</b>		
SUZUKI	GRAND VITARA	

### Cabin Filter

Maker	Model	Application
<b>FB5016 ( OE No : 87139YZZ08 )</b>		
TOYOTA	HILUX	
<b>FB5017 ( OE No : CU1827 )</b>		
SUZUKI	SWIFT	
<b>FB5018 ( OE No : CU2513 )</b>		
SUZUKI	GRAND VITARA	
<b>FB5019 ( OE No : CU24001 )</b>		
SUZUKI	KIZASHI	
<b>FB5020 ( OE No : CU220022 )</b>		
SUZUKI	GRAND VITARA	
<b>FB5021 ( OE No : CUK1827 )</b>		
SUZUKI	SWIFT	
<b>FB5022 ( OE No : CU17001 )</b>		
SUZUKI	CELERIO	
<b>FB5023 ( OE No : AC939EX )</b>		
SUZUKI	IGNIS	
<b>FB5024 ( OE No : 9586181P00 )</b>		
SUZUKI	SWIFT	
<b>FB5025 ( OE No : 272774BU0A )</b>		
NISSAN	QASHQAI	
<b>FB5026 ( OE No : BBM461J6X )</b>		
MAZDA	3	
<b>FB5027 ( OE No : 999M1VP055 )</b>		
NISSAN	ARMADA	
<b>FB6001 ( OE No : B729800QAA )</b>		
RENAULT	CLIO	
<b>FB6002 ( OE No : 272774812R )</b>		
RENAULT	ESPACE	
<b>FB6003 ( OE No : 27891JY15A )</b>		
RENAULT SAMSUNG	QM5	